

# DocuPrint 3055/2065

## PCL printer driver Release-note

20 November 2009

Fuji Xerox Controller Development Group  
Software Platform Development

### ❑ Products

DocuPrint 3055  
DocuPrint 2065

### ❑ Environment and File name and File size

Windows 2000/XP/Vista/Server 2003/ Server 2008/ 7 (x86)  
Windows XP/Vista/Server 2003/ Server 2008/ 7 (x64)

#### English

(x86) fxdp3055pcl609110w2k3ien.zip	2,831,348 byte
(x64) fxdp3055pcl609110w2k3iex.zip	3,203,678 byte

#### Korean

(x86) fxdp3055pcl609110w2k3iko.zip	2,823,924 byte
(x64) fxdp3055pcl609110w2k3iex.zip	3,195,686 byte

#### SimplifiedChinese

(x86) fxdp3055pcl609110w2k3isc.zip	2,826,388 byte
(x64) fxdp3055pcl609110w2k3iex.zip	3,194,337 byte

#### TraditionalChinese

(x86) fxdp3055pcl609110w2k3itc.zip	2,825,983 byte
(x64) fxdp3055pcl609110w2k3iex.zip	3,194,399 byte

### ❑ Stored location

#### English

(x86) <http://www.comg.ksp.fujixerox.co.jp/PCL/Teak/fxdp3055pcl609110w2k3ien.zip>  
(x64) <http://www.comg.ksp.fujixerox.co.jp/PCL/Teak/fxdp3055pcl609110w2k3iex.zip>

#### Korean

(x86) <http://www.comg.ksp.fujixerox.co.jp/PCL/Teak/fxdp3055pcl609110w2k3iko.zip>  
(x64) <http://www.comg.ksp.fujixerox.co.jp/PCL/Teak/fxdp3055pcl609110w2k3iex.zip>

#### SimplifiedChinese

(x86) <http://www.comg.ksp.fujixerox.co.jp/PCL/Teak/fxdp3055pcl609110w2k3isc.zip>  
(x64) <http://www.comg.ksp.fujixerox.co.jp/PCL/Teak/fxdp3055pcl609110w2k3iex.zip>

#### TraditionalChinese

(x86) <http://www.comg.ksp.fujixerox.co.jp/PCL/Teak/fxdp3055pcl609110w2k3itc.zip>  
(x64) <http://www.comg.ksp.fujixerox.co.jp/PCL/Teak/fxdp3055pcl609110w2k3iex.zip>

### ❑ Version and Release date

#### English/ Korean/ SimplifiedChinese/ TraditionalChinese

(x86) V2.6.6.1	2009/ 8/ 24
(x64) V2.6.6.1	2009/ 8/ 24

### ❑ Appendix to readme file

None.

### ❑ Virus Check

Confirmed.

### ❑ Changed Items

Actions taken in response to the troubles reported from the field and tests and the major changing in the tests.

The Following items, Fixed Problems and Specification Changes, are changes from FX DocuPrint 3055/2065 PCL Driver Version 2.6.5(1/10).

Fixed Problems:

AR No.	Proweb No.	OS	Description of the Changes
117081	-	Win2k/XP/ Vista	<FC>Acrobat Reader Crush (Problem of TrueType Glyph).
120431	-	Win2k/XP/ Vista	WLK 1.4 Rendering Test(PGremlin2) Fail.
120516	46285	Win2k/XP/ Vista	<FC Drv-CFT>(Proweb 46285) At the time of printer addition, it is fxzjvup.dll exception error outbreak.
121895	-	Win2k/XP/ Vista	<PF2.7r4p2> Revision the problem that personal setting information is deleted at the time of shared printer icon deletion.
16424	-	Win2k/XP/ Vista	In the USB port where StatusMonitor was not installed, after having made ONLINE with a spooler from a state of the printer power supply OFF forcibly, when data are transmitted by a timing of the whole power supply ON – initialization of the printer, there is the case that but a job stays to a spooler after the print end.

☐ Limitations

None.

☐ Known Problems

None.

☐ WHQL Certified

Certified.

☐ Appendix

The details of the problem are described following below.

AR No.	OS	Title	Reproduction Method or Details

Other ARs are fixed, these problems are slight.

-- End of Document. --